
START 3

Superfund Technical Assessment and Response Team 3 –
Region 8



United States
Environmental Protection Agency
Contract No. EP-W-05-050

2011 SOURCE WATER INVESTIGATION REPORT

RICO-ARGENTINE ST. LOUIS TUNNEL
Rico, Dolores County, Colorado

TDD No. 1005-01

MARCH 20, 2012



URS

OPERATING SERVICES, INC.

In association with:

Garry Struthers Associates, Inc.
LT Environmental, Inc.
TechLaw, Inc.
Tetra Tech EMI
TN & Associates, Inc.

**RICO ARGENTINE ST. LOUIS TUNNEL
2011 MINE INVESTIGATION REPORT
Rico, Dolores County, Colorado**

TABLE OF CONTENTS

	<u>PAGE #</u>
1.0 INTRODUCTION	1
2.0 BACKGROUND	3
2.1 Site History	
2.2 Mine Workings	
3.0 SAMPLE COLLECTION AND ANALYSIS	6
3.1 Ions	
3.2 Dye Tracers	
3.3 Total and Dissolved Metals, Anions, and Hardness	
3.4 Stable Water Isotopes and Tritium	
4.0 STREAMFLOW INVESTIGATION	10
4.1 High Flow Stream Tracer Study (June 2011)	
4.1.1 Slug Additions	
4.1.2 Stage-Discharge Relationships	
4.1.3 Slug Adjustments	
4.1.4 Spatial 'Snapshots' of Streamflow.	
4.1.5 Streamflow Loss at High Flow	
4.2 Low Flow Stream Tracer Study (October 2011)	
4.2.1 Slug Injections	
4.2.2 Stage-Discharge Relationships	
4.2.3 Slug Adjustments	
4.2.4 Spatial Bromide Profiles	
4.2.5 Streamflow Loss at Low Flow	
5.0 MINE CHARACTERIZATION	18
5.1 517 Shaft Access Tunnel	
5.2 Blaine Tunnel	
5.3 Argentine Tunnel	
6.0 MINE WATER FLOW INVESTIGATION	21
6.1 517 Shaft Tracer Injection	
6.2 517 Shaft Tracer Results:	
6.3 Blaine Tunnel Tracer Injection	
6.4 Blaine Tunnel Tracer Results	
6.5 Silver Creek Tracer Injection and Results	
6.6 Potential Diversion to Argentine Tailings	